




**TEXIGLASS**

**TECIDOS DE FIBRA**  
**VIDRO • CARBONO • ARAMIDA**

# Presença da TEXIGLASS no mundo





# Fios dos Tecidos

**Os fios podem ser de:**

**Fibra de Vidro**

**Fibra de Carbono**

**Fibra Aramida (Kevlar ou Twaron)**

**Outras Fibras**

# Tecido de Fibra de Vidro





# Tecido de Fibra de Carbono CCS-200



**Fibra de Carbono = fio acrílico carbonizado**

# Tecido de Fibra Aramida KK-205



# **Tecido Híbrido Carbono + Aramida CKS-200**



**Material**

**Densidade  
(g/cm<sup>3</sup>)**

**Mód. de  
Elast. E  
(GPa)**

**Resist. à  
Tração  
(MPa)**

**Aço 1010**

**7,87**

**207**

**365**

**Alumínio 6061**

**2,70**

**69**

**310**

**Compósito  
Carbono+Epoxi**

**1,50**

**138**

**1550**

**Compósito  
Aramida+Epóxi**

**1,29**

**76**

**1378**

**Compósito Vidro  
E+Epóxi**

**2,00**

**39**

**965**

**Material**

**Densidade  
(g/cm<sup>3</sup>)**

**Mód. de  
Elast. E  
(GPa)**

**Resist. à  
Tração  
(MPa)**

**Aço 1010**

**7,87**

**207**

**365**

**Alumínio 6061**

**2,70**

**69**

**310**

**Compósito  
Carbono+Epoxi**

**1,50**

**138**

**1550**

**Compósito  
Aramida+Epóxi**

**1,29**

**76**

**1378**

**Compósito Vidro  
E+Epóxi**

**2,00**

**39**

**965**

**Material**

**Densidade  
(g/cm<sup>3</sup>)**

**Mód. de  
Elast. E  
(GPa)**

**Resist. à  
Tração  
(MPa)**

**Aço 1010**

**7,87**

**207**

**365**

**Alumínio 6061**

**2,70**

**69**

**310**

**Compósito  
Carbono+Epoxi**

**1,50**

**138**

**1550**

**Compósito  
Aramida+Epóxi**

**1,29**

**76**

**1378**

**Compósito Vidro  
E+Epóxi**

**2,00**

**39**

**965**

# Quanto Maior o Conteúdo de Carbono, Maior é o Módulo de Elasticidade (E)



<b>Tipo</b>	<b>Densidade</b> <b>g/cm<sup>3</sup></b>	<b>Módulo (E)</b> <b>GPa</b>
<b>Standard Módulo</b>	<b>1,76</b>	<b>228</b>
<b>Alto Módulo</b>	<b>1,90</b>	<b>400</b>
<b>Ultra-Alto Módulo</b>	<b>1,86</b>	<b>517</b>

# - Por que usar TECIDOS?

## - Usam-se tecidos por várias razões:

Com tecidos obtém-se

- 1 – Estabilidade dimensional.
- 2 – Garantia de uniformidade na espessura.
- 3 – Cálculos precisos de resistência mecânica.  
(maior segurança)
- 4 – Redução de peso.

# Tecelagem 8HS Crow Foot

**50% de Composites**

**20% de redução de peso**

**Menor Peso**

**Maior Autonomia**

**Maior Capacidade de carga**

**Menor Poluição**

**1 Kg a menos de peso**

**2 m a menos de pista**

# **Futuro das Aeronaves**

**No futuro, a preocupação ambiental será o grande desafio.**

**A próxima geração de aeronaves deverá ter mais compósitos na fuselagem.**

**Maior eficiência em consumo de combustível.**

**Meta: Consumo equivalente a 30% do atual (ou seja, 70% mais econômicas).**

**Aeronaves "amigas da natureza".**

## **Por que?**

**O tráfego aéreo deverá dobrar até 2020 e triplicar até 2050.**

**Como os custos da aviação quadruplicaram desde 1990, a eficiência será o grande trunfo.**

**E isso só conseguiremos com os compósitos, que proporcionam liberdade de design e total inovação na fuselagem das aeronaves.**

**Há os exemplos da AIRBUS e da BOEING, entre outras.**

## Por que compósitos?



# 'WE LOST THE CABIN'

BY CLIVE IRVING

**A**t 10:56 p.m. on April 1 last year, Southwest Airlines Flight 812, en route from Phoenix to Sacramento with 118 passengers aboard, was completing its climb to its cruise altitude of 36,000 feet. An air-traffic controller at Los Angeles Center had just acknowledged a routine call from the pilot. But within a minute or so the controller became aware that Flight 812 was in some kind of trouble. The messages were garbled until, finally, he heard the pilot clearly: "...declaring an emergency we lost the cabin."

Shawna Malvini Redden, a 29-year-old doctoral student at Arizona State, had just settled into a window seat in row 8 when there was an ear-splitting bang. Oxygen masks dropped from the ceiling and the airplane pitched forward.

The Los Angeles controller asked the pilot to repeat the message. "*Request an emergency descent we've lost the cabin and we're starting down.*"

"We lost the cabin" meant that the

airplane had suffered a sudden and extreme loss of cabin pressure. The pilots had two urgent priorities—to get to a lower altitude and to find an airport for an emergency landing.

As a blast of air rushed through the cabin, Malvini Redden felt reassured by the flight attendants' composure. But she reached over to the man in the aisle seat and took his hand. "If I'm going to go down," she thought, "at least I want to feel connected to somebody."

Flight 812 touched down safely a few minutes later in Yuma, Ariz., a hole 59 inches long and nine inches wide in the roof of the cabin. The skin of the airplane had peeled away. To inspectors from the National Transportation Safety Board, the structural failure must have seemed worryingly familiar: there had been a similar episode involving another Southwest airplane in July 2009; additionally, the airplane type involved, the Boeing 737, had a history of weaknesses in its fuselage skin. When the NTSB took the damaged part of the

cabin roof from Flight 812 back to its labs in Washington, they found serious manufacturing flaws. Forty-two rivet holes at joints where the fuselage skin overlapped, called lap joints, were so far out of alignment that the lower holes had become oval, not round, causing fatigue cracks, and paint had leaked from the outer skin into the joints.

This specific plane had been delivered in 1996, a version of the 737 known as the Classics. Immediately after the Flight 812 emergency, Boeing's chief engineer for the series, Paul Richter, said that Boeing had anticipated some level of cracking in the relevant area, but not so soon in the plane's life cycle. And the CEO of Boeing Commercial Airplanes, W. James McNerney, asserted that the problem was poor manufacturing of one airplane, not a broader design issue.

The 737 Classics were supposed to have a safe service life of 60,000 flights. In fact, to meet that standard, they must be judged to be capable of flying twice that number. But the Southwest



## Por que compósitos?

# 'WE LOST THE CABIN'

BY CLIVE IRVING

**A**t 10:56 p.m. on April 1 last year, Southwest Airlines Flight 812, en route from Phoenix to Sacramento with 118 passengers aboard, was completing its climb to its cruise altitude of 36,000 feet. An air-traffic controller at Los Angeles Center had just acknowledged a routine call from the pilot. But within a minute or so the controller became aware that Flight 812 was in some kind of trouble. The messages were garbled until, finally, he heard the pilot clearly: "...declaring an emergency we lost the cabin."

Shawna Malvini Redden, a 29-year-old doctoral student at Arizona State, had just settled into a window seat in row 8 when there was an ear-splitting bang. Oxygen masks dropped from the ceiling and the airplane pitched forward.

The Los Angeles controller asked the pilot to repeat the message. "Request an emergency descent we've lost the cabin and we're starting down."

"We lost the cabin" meant that the

airplane had suffered a sudden and extreme loss of cabin pressure. The pilots had two urgent priorities—to get to a lower altitude and to find an airport for an emergency landing.

As a blast of air rushed through the cabin, Malvini Redden felt reassured by the flight attendants' composure. But she reached over to the man in the aisle seat and took his hand. "If I'm going to go down," she thought, "at least I want to feel connected to somebody."

Flight 812 touched down safely a few minutes later in Yuma, Ariz., a hole 59 inches long and nine inches wide in the roof of the cabin. The skin of the airplane had peeled away. To inspectors from the National Transportation Safety Board, the structural failure must have seemed worryingly familiar: there had been a similar episode involving another Southwest airplane in July 2009; additionally, the airplane type involved, the Boeing 737, had a history of weaknesses in its fuselage skin. When the NTSB took the damaged part of the

cabin roof from Flight 812 back to its labs in Washington, they found serious manufacturing flaws. Forty-two rivet holes at joints where the fuselage skin overlapped, called lap joints, were so far out of alignment that the lower holes had become oval, not round, causing fatigue cracks, and paint had leaked from the outer skin into the joints.

This specific plane had been delivered in 1996, a version of the 737 known as the Classics. Immediately after the Flight 812 emergency, Boeing's chief engineer for the series, Paul Richter, said that Boeing had anticipated some level of cracking in the relevant area, but not so soon in the plane's life cycle. And the CEO of Boeing Commercial Airplanes, W. James McNerney, asserted that the problem was poor manufacturing of one airplane, not a broader design issue.

The 737 Classics were supposed to have a safe service life of 60,000 flights. In fact, to meet that standard, they must be judged to be capable of flying twice that number. But the Southwest



Por que compósitos?

# 'WE LOST THE CABIN'

BY CLIVE IRVING

At 10:56 p.m. on April 1 last year, Southwest Airlines Flight 812, en route from Phoenix to Sacramento with 118 passengers aboard, was completing its climb to its cruise altitude of 36,000 feet. An air-traffic controller at Los Angeles International Airport, aware of a routine climb, was not aware of a kind of garbled until, finally, he heard the pilot clearly: "...declaring an emergency we lost the cabin."

Shayna Mahvot Redden, a 29-year-old doctoral student at Arizona State, had just rowed a boat on the bay. She was on the wing and the airplane pitched forward.

The Los Angeles controller asked the pilot to repeat the message. "Request an emergency descent we've lost the cabin and we're starting down."

"We lost the cabin" meant that the

airplane had suffered a sudden and extreme loss of cabin pressure. The pilots had two urgent priorities—to get to a lower altitude and to find an airport for an emergency landing.

As a blast of air rushed through the cabin, passengers felt reassured by composure. But a man in the aisle said, "If I'm going to die, at least I want to feel connected to somebody."

Flight 812 touched down safely a few minutes later in Yuma, Ariz., a hole 59 inches long and nine inches wide in the roof of the cabin. The skin of the fuselage had pulled away from the structure. The hole must have seemed worryingly familiar: there had been a similar episode involving another Southwest airplane in July 2009; additionally, the airplane type involved, the Boeing 737, had a history of weaknesses in its fuselage skin. When the NTSB took the damaged part of the

cabin roof from Flight 812 back to its labs in Washington, they found serious manufacturing flaws. Forty-two rivet holes at joints where the fuselage skin overlapped, called lap joints, were so far out of alignment that the lower holes had become oval, not round, causing fatigue cracks, and paint had leaked from the outer skin into the joints.

This specific plane had been delivered in 1996, a version of the 737 known as the Classics. Immediately after the Flight 812 emergency, Boeing's chief engineer for the series, Paul Richter, said that Boeing had anticipated some level of cracking in the relevant area, but not so soon in the plane's life cycle. And the CEO of Boeing Commercial Airplanes, W. James McNerney, asserted that the problem was poor manufacturing of one airplane, not a broader design issue.

The 737 Classics were supposed to have a safe service life of 60,000 flights. In fact, to meet that standard, they must be judged to be capable of flying twice that number. But the Southwest

Despressurização da cabine


Por que isso ocorre? → Fadiga!!!

**AIR PRESSURE INSIDE A PLANE INCREASES  
DRAMATICALLY WITH ALTITUDE. THIS STRESS CAN  
WEAKEN THE PLANE'S SKIN OVER TIME.**




CROSS SECTION OF A 737 FUSELAGE SHOWN BELOW

At the gate



When on the ground, air pressure is equal inside and outside the plane.

At cruise




At 35,000 feet, inside air pressure is greater than outside, like a balloon.


**AIR PRESSURE INSIDE A PLANE INCREASES  
DRAMATICALLY WITH ALTITUDE. THIS STRESS CAN  
WEAKEN THE PLANE'S SKIN OVER TIME.**



**A pressão interna pode exercer uma força  
De até ½ tonelada sobre as paredes da cabine.**



When on the ground, air pressure is equal inside and outside the plane.



At 35,000 feet, inside air pressure is greater than outside, like a balloon.

**O metal é dúctil**

**A pressão interna da cabine estica as paredes da aeronave**

**Cada vez que a cabine é presssurizada, as paredes afinam.**


**As paredes da aeronave afinam constantemente.**

**Como o metal é dúctil, mas não elástico, ele não volta.**

**A cada ciclo, a fuselagem é submetida a intenso “stress”**

**A vida de uma aeronave não é medida em “anos” mas em “ciclos”**

**Os compósitos de fibra de carbono ou mesmo fibra de vidro, como praticamente não esticam, sofrem muito menos “stress”.**



From left: Richard Garcia—AFP-Getty Images, Robert Nichols—AP

## Investigators said humid conditions weakened Aloha's 737 in 1988

Newsweek



**BOEING 737**



**BOEING 747**

**Enorme diferença de tamanho entre o Boeing 737 e o 747  
Só com Compósitos se pode chegar a esse resultado!**



Especialmente para o 747-8 a GE desenvolveu uma turbina com **fibra de carbono**, Com menor N<sup>o</sup> de pás, mais silenciosa, mais econômica e muito **mais leve**. 180 Kg a menos por turbina => x 4 turbinas, são **10 passageiros a mais!**

***EFICIÊNCIA!!!***



**525 passageiros**

**A-380**

**Comprimento: 73m**

**Envergadura: 80m**

**Peso Vazio: 277 ton**

**Peso Máximo: 580 ton**

**Autonomia: 15.000 Km**

**Velocidade: 945 Km/h**



**460 passageiros**

**BOEING 747-8**

**Velocidade: 988 Km/h**

**Comprimento: 76m**

**Envergadura: 68m**

**Peso máximo: 397 ton**

**Autonomia: 15.000 Km**



**Radome do Air-Bus A-320  
Oficina da TAM em São Carlos - SP**

14 4 2008



**Radome do Air-Bus A-320  
Oficina da TAM em São Carlos - SP**

# Peças para Avião Executivo



Laminação de Fibra de carbono  
pré-impregnada com resina  
epóxi.



Produto final  
após cura em  
autoclave.

# Produtos



**Aeroespacial**









**Obrigado pela atenção**



**Giorgio Solinas**

**giorgio@texiglass.com.br**

**+ 55.19.3856-4278**